

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	12	(strain stress ) near3 (gauge sens\$4 detect\$4 transducer measur\$4 ) near3 (soil dirt ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/10/31 09:59
L2	2	1 and (torque ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/10/31 09:59
L3	5	1 and (torque )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/10/31 10:00
L4	147	(strain stress ) near3 (gauge sens\$4 detect\$4 transducer measur\$4 ) near3 (soil dirt )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/10/31 09:59
L5	15	4 and (torque )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2005/10/31 10:00